FORM B - BUILDING

MASSACHUSETTS HISTORICAL COMMISSION MASSACHUSETTS ARCHIVES BUILDING 220 MORRISSEY BOULEVARD BOSTON, MASSACHUSETTS 02125

Photograph



Locus Map



Recorded by: Stacy Spies, Historic Preservation Consultant

Organization: for Chelmsford Land Conservation Trust

Date (month / year): January 2023

Assessor's Number	USGS Quad	Area(s)	Form Number
65/ 271/ 12/ /	Billerica		

Town/City: Chelmsford

Place: (neighborhood or village):

Address: 116 Riverneck Road

Historic Name: Dunbar House

Uses: Present: Single Family Dwelling

Original: Outbuilding

Date of Construction: Ca. 1920-1940s

Source: Visual Assessment

Style/Form: None

Architect/Builder: Not known

Exterior Material:

Foundation: Stone, Uncut; Concrete Block

Wall/Trim: Vinyl siding

Roof: Rolled bituminous roofing

Outbuildings/Secondary Structures: Two sheds

Major Alterations (with dates): Vinyl siding; Metal-frame

storm windows

Condition: Poor

Moved: no ☐ yes ☐ Date:

Acreage: 0.26 acre

Setting: Mixed residential and light industrial. Chelmsford Fire Department Engine #4 House is located across the street. The Canal Street Conservation Area abuts the property to the south. St. Joseph's Cemetery is located south and east of the property. Highways Interstate 495

and U.S. Route 3 are located nearby.

CHELMSFORD

Area(s)	Form No.

MASSACHUSETTS HISTORICAL COMMISSIC	N
220 Morrissey Boulevard, Boston, Massachusetts	0212

☐ Recommended for listing in the National Register of Historic Places.
If checked, you must attach a completed National Register Criteria Statement form.

Use as much space as necessary to complete the following entries, allowing text to flow onto additional continuation sheets.

ARCHITECTURAL DESCRIPTION:

Describe architectural features. Evaluate the characteristics of this building in terms of other buildings within the community.

The diminutive house (less than 500 square feet) appears to be a collection of former outbuildings constructed during the second quarter of the 20th century that have been assembled as one building. The living room block is capped with a shallow-pitched side-gabled roof. The façade, now sheltered by a small enclosure, contains a 2/2 wood sash window and a paneled wood door with a large light in the top half. A vinyl sash window is centered in the block's west elevation. The interior is finished with a wood plank floor and a beadboard ceiling. Beadboard was also used to construct a closet located in the northwest corner of the room. Window and door surrounds are wide, flat boards with thick sills (perhaps 2x4s). A slender brick chimney with an opening for a stove pipe is located in the east end of the room.

The southwest room of the house consists of a shed-roof block. A row of three 6-light, wood-framed hopper windows fills the south elevation. A similar, single, hopper window and a paneled wood door similar to that at the main entrance are located in the west elevation. A multi-light, wood-frame slider window in the north elevation connects the room to the main block. Window and door surrounds are wide, flat boards with narrow sills. A shed-roof block attached to the house's east elevation contains the kitchen, the interior of which is also finished with beadboard. The small space at the rear of the house between the bedroom and kitchen connects the two formerly-free-standing outbuildings. A slender brick stovepipe chimney is located in the south wall of the connecting area. A small bathroom ell is located at the southeast corner of the house.

HISTORICAL NARRATIVE

Discuss the history of the building. Explain its associations with local (or state) history. Include uses of the building, and the role(s) the owners/occupants played within the community.

This apparent collection of former outbuildings is located on the former Ohlson property. In 1881, Swedish immigrant Sven Ohlson purchased a ten-acre parcel of land here that extended west to the Middlesex Canal (now Canal Street). The family appears to have constructed a house on the property and were living in it by 1900. The 1900 census included Helen Ohlson, Sven's widow, and her grown children Elmer Ohlson, Ebba Ohlson, and Amanda Ohlson Logan. Amanda R. Ohlson Logan (1863-1948), who had been widowed by the time of the 1910 census, worked as a nurse. Amanda Ohlson purchased the property from her siblings in 1920 and lived here alone until her death. The Ohlson family sold the property in 1949.

At some point in time between 1950 and 1965, a building (presumably the former Ohlson house), was removed or demolished.³ An account relayed by neighbors states that the house burned during that time and the former outbuildings were assembled to create a dwelling.⁴ (More research is recommended.)

In 1969, Donald F. Burbank purchased the dwelling and the 0.26-acre lot.⁵ Born in Lowell, Donald F. Burbank (1933- 2021)⁶ worked as a self-employed tree surgeon for almost fifty years and planted numerous flowering specimen trees on the lot. Donald Burbank bequeathed the property to the Chelmsford Land Conservation Trust. The Trust has named the property the Burbank Gardens and will be open to the public.⁷

¹ Middlesex County South Registry of Deeds Book 143, p. 517.

² Middlesex County South Registry of Deeds Book 1109, p. 68.

³ U.S.G.S. Billerica Quadrangle map. 1950 and 1965.

⁴ Conversation. Scott Venier, Chelmsford Conservation Land Trust to Stacy Spies, Jan. 18, 2023.

⁵ Middlesex County South Registry of Deeds Book 1902, p. 602.

⁶ https://www.legacy.com/us/obituaries/lowellsun/name/donald-burbank-obituary?id=24561998. Accessed Jan. 20, 2023.

⁷ https://www.clct.org/burbank-arboretum/. Accessed Jan. 20, 2023.

CHELMSFORD

116 RIVERNECK ROAD

Form No. Area(s)

MASSACHUSETTS HISTORICAL COMMISSION

220 Morrissey Boulevard, Boston, Massachusetts 02125

BIBLIOGRAPHY and/or REFERENCES

Chelmsford City Directories. Ancestry.com.

Chelmsford Tax Assessor records. 2018.

Findagrave.com.

Historicaerials.com. Aerial photographs. 1963. 1965. 1971. 1978. Accessed Jan. 20, 2023.

Lowell City Directories. Ancestry.com.


Middlesex North Registry of Deeds.

United States Census. Ancestry.com

United States Geological Survey. Billerica, Massachusetts. 1:24000. 1941, 1950, 1965.

Walker, George H. & Co. Atlas of Middlesex County. Boston: George H. Walker & Co., 1889.

SUPPLEMENTARY INFORMATION



Assessor's plan.



View looking southwest. From right to left: porch, main room, kitchen (with shed roof), and bathroom ell.



View looking north. Bedroom at left, bathroom at right.

CHELMSFORD

116 RIVERNECK ROAD

Area(s) Form No.

MASSACHUSETTS HISTORICAL COMMISSION 220 Morrissey Boulevard, Boston, Massachusetts 02125



View looking east.



Detail. Main entrance. View looking west.



View looking north toward closet on north wall. Entrance visible at right.



View looking northwest from southwest room toward west elevation. Note 6-light hopper window.

CHELMSFORD

116 RIVERNECK ROAD

Area(s)	Form No.
---------	----------

MASSACHUSETTS HISTORICAL COMMISSION 220 Morrissey Boulevard, Boston, Massachusetts 02125



View looking north from southwest room toward main room. Note sliding window between the rooms.